

Materials Sampling Guide

Table of Contents

Section 7

Mineral Aggregate for Armor Coat

1. Mineral Aggregate for Armor Coat.....Page 7-1

DATE: 08-23-00
REVISED: 07-12-02

Minimum Material Certificate, Sample and Inspection Requirements							
MATERIAL	TYPE OF TEST	Q.C. SAMPLING AND TESTING BY CONTRACTOR	VERIFICATION SAMPLING AND TESTING BY NDOR			LOCATION OF ADDITIONAL INFORMATION	
SECTION: 7 – Mineral Aggregate for Armor Coat			FIELD PERSONNEL	BRANCH LAB	LINCOLN LAB	NOTE No.	PAGE No.
1) Mineral Aggregate for Armor Coat	Quality & Gradation	-----	<p>See Standard Specifications, Supplemental Specifications, and/or the Project Special Provisions for Mineral Aggregate for Armor Coat sampling and testing requirements.</p> <p>Project personnel will provide the 12 and 60 pound samples needed to perform the testing shown under the Lincoln Lab column.</p> <p>The sample shall be taken at the project.</p>	-----	<p>One 60 pound sample for quality tests first 1,000 cubic yards. If so designated on the "Source of Aggregates to Be Used" form.</p> <p>One 12 pound sample for gradation tests each 1000 cubic yard or fraction thereof. (Duplicate of sample tested in the field).</p>	4	5